

VIN REPORT

2B3CL3CG5BH516692 ↗

DODGE CHARGER

2011 2011 DODGE CHARGER

FIRST SEEN	LAST SEEN	DAYS TRACKED
—	—	—

- 1 listing
- 1 damage event
- Source · IAAI
- Lot #38254546



ODOMETER	BODY	TRANSMISSION	DRIVETRAIN	PRIMARY DAMAGE	CONDITION
167,017 mi	—	Automatic	REAR WHEEL DRIVE	Rear	Listed (auction)

Sale price across listings USD · 0 data points

Not enough auction data yet.

All listings · 1

DATE	SOURCE	LOT ID	DAMAGE	STATUS	PRICE	LINK
—	IAAI	#38254546	Rear	—	—	Open →

Specs

VIN · 2B3CL3CG5BH516692

Year	2011	Make	DODGE
Model	CHARGER	Body	—
Engine	3.6L 24-VALVE VVT V6 ENGINE	Transmission	Automatic
Drivetrain	REAR WHEEL DRIVE	Fuel	Gasoline
Cylinders	6	Odometer	167,017 mi
Color	● Black	Title	2011 DODGE CHARGER
Location	Pulaski (VA)	Primary damage	Rear
Secondary	Left front	VIN status	Unknown

Vehicle history

1 event · first seen —

LISTINGS

1

FIRST SEEN

—

LAST SOLD PRICE

—

- **Listed** —
IAAI · Pulaski (VA)