

VIN REPORT

# 3VWD17AJ2FM211198 ↗

VOLKSWAGEN JETTA SE  
2015 2015 VOLKSWAGEN JETTA SE

FIRST SEEN	LAST SEEN	DAYS TRACKED
—	—	—

- 1 listing
- 1 damage event
- Source · Copart
- Lot #77620313



ODOMETER	BODY	TRANSMISSION	DRIVETRAIN	PRIMARY DAMAGE	CONDITION
—	—	<b>Automatic</b>	<b>FRONT WHEEL DRIVE</b>	<b>Burn</b>	<b>Listed (auction)</b>

**Sale price across listings** USD · 0 data points

Not enough auction data yet.

**All listings · 1**

DATE	SOURCE	LOT ID	DAMAGE	STATUS	PRICE	LINK
—	<span style="background-color: #4a90e2; color: white; border-radius: 15px; padding: 2px 5px;">COPART</span>	#77620313	<span style="background-color: #f08080; color: white; border-radius: 15px; padding: 2px 5px;">Burn</span>	<span style="background-color: #4a90e2; color: white; border-radius: 15px; padding: 2px 5px;">E</span>	—	Open →

**Specs**

VIN · 3VWD17AJ2FM211198

Year	2015	Make	VOLKSWAGEN
Model	JETTA SE	Body	—
Engine	1.8L 4	Transmission	Automatic
Drivetrain	FRONT WHEEL DRIVE	Fuel	Gas
Cylinders	4	Odometer	—
Color	● White	Title	2015 VOLKSWAGEN JETTA SE
Location	CA - SAN JOSE	Primary damage	Burn
Secondary	Missing/altered vin	VIN status	Unknown

**Vehicle history**

1 event · first seen —

LISTINGS <b>1</b>	FIRST SEEN —	LAST SOLD PRICE —
<p>— <input checked="" type="radio"/> <b>E</b> —</p> <p>Copart · CA - SAN JOSE</p>		