

VIN REPORT

JTHBA1D24K5096176 ↗

LEXUS IS 300

2019 2019 LEXUS IS 300

FIRST SEEN	LAST SEEN	DAYS TRACKED
—	—	—

- 1 listing
- 1 damage event
- Source · Copart
- Lot #53512894



ODOMETER 27,230 mi	BODY —	TRANSMISSION Automatic	DRIVETRAIN REAR WHEEL DRIVE	PRIMARY DAMAGE Rear end	CONDITION Listed (auction)
-----------------------	-----------	---------------------------	--------------------------------	----------------------------	-------------------------------

Sale price across listings USD · 0 data points

Not enough auction data yet.

All listings · 1

DATE	SOURCE	LOT ID	DAMAGE	STATUS	PRICE	LINK
—	COPART	#53512894	Rear end	E	—	Open →

Specs

VIN · JTHBA1D24K5096176

Year	2019	Make	LEXUS
Model	IS 300	Body	—
Engine	2.0L 4	Transmission	Automatic
Drivetrain	REAR WHEEL DRIVE	Fuel	Gas
Cylinders	4	Odometer	27,230 mi
Color	● Silver	Title	2019 LEXUS IS 300
Location	AL - MONTGOMERY	Primary damage	Rear end
Secondary	—	VIN status	Unknown

Vehicle history

1 event · first seen —

LISTINGS 1	FIRST SEEN —	LAST SOLD PRICE —
<p>— <input checked="" type="radio"/> E —</p> <p>Copart · AL - MONTGOMERY</p>		