

VIN REPORT

JTHBW1GGXD2014898 ↗

LEXUS ES 300H

2013 2013 LEXUS ES 300H

• 1 listing
1 damage event
Source · Copart
Lot #53441524

FIRST SEEN	LAST SEEN	DAYS TRACKED
Jun 2024	Jun 2024	700



ODOMETER 109,800 mi	BODY —	TRANSMISSION Automatic	DRIVETRAIN FRONT WHEEL DRIVE	PRIMARY DAMAGE Rear end	CONDITION Listed (auction)
------------------------	-----------	---------------------------	---------------------------------	----------------------------	-------------------------------

Sale price across listings USD · 0 data points

Not enough auction data yet.

All listings · 1

DATE	SOURCE	LOT ID	DAMAGE	STATUS	PRICE	LINK
Jun 17, 2024	COPART	#53441524	Rear end	• F	—	Open →

Specs

VIN · JTHBW1GGXD2014898

Year	2013	Make	LEXUS
Model	ES 300H	Body	—
Engine	2.5L 4	Transmission	Automatic
Drivetrain	FRONT WHEEL DRIVE	Fuel	Hybrid Engine
Cylinders	4	Odometer	109,800 mi
Color	● White	Title	2013 LEXUS ES 300H
Location	NC - CHINA GROVE	Primary damage	Rear end
Secondary	Side	VIN status	Unknown

Vehicle history

1 event · first seen Jun 2024

LISTINGS

1

FIRST SEEN

Jun 2024

LAST SOLD PRICE

—

Jun 17, 2024 ● F

Copart · NC - CHINA GROVE

—